Work Orde		16					·			:		Page 1
	D4012-1		A	Accept				s	etup	Start Stop	• • • • • • • • • • • • • • • • • • • •	18 181 1181 1881 18 118 1181 1881
	Cushion 14/04/2010 22/04/2010	Start Qty: 40.0 Req'd Qty: 40.0			Cust Ite Custom					1 : ! ! ! !		
Approvals:	Process Pla	n:	Date:	Tooling: SPC (Y/N):		Date:		ŀ	Run	Start		
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hours	Draw Numb	Drav er Rev.	v Plan Code	Accept Qty	Rej Qty	'!	Reject Number	Insp. Stamp
Draw Nbr	Rev	ision Nbr					+					
D4012	A				-					 		
100 Doosan		Memo		0.00					<u> </u>			
Doosan Lathe		FOLIO DWG I	as per folio FA & dwg D REV: N/A REV: A	لل	10/07/01		4					
		QC2- Inspect parts	off machine FAI/FAIB	0.00 کلہ	10/07/01			,				

Quality Control

D	art	Ae	rosi	pace	Ltd
_	~	,,,,,		Puv	

W/O:			W	ORK ORDER CHANG	iES					
DATE	STEP	PRO	CEDURE CH	ANGE	By	/	Date	Qty	Approval QC Inspector	
	:									
· · · · · · · · · · · · · · · · · · ·										
Part No		PAR #:							Date:	· · · · · · · · · · · · · · · · · · ·
Resolution:								ļ.,		
NCR:		V	ORK ORD	ER NON-CONFORM	ANCE (N	CR)				
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Sect Action Description Chief Eng		gn & ate	Verifica Section		Approval Chief Eng	Approval QC Inspector
				Office any		<u> </u>				
						·				
NOTE: D	1 0 :									

April 14, 2010 10:11:32 AM

Item ID:

D4012-1

Accept



Setup Start



Stop



Revision ID:

Item Name:

Cushion

Start Date: 14/04/2010 **Required Date: 22/04/2010**

Start Qty: 40.00

Req'd Qty: 40.00

Cust Item ID: Customer:

Run

Start



Reference: Approvals:

Process Plan:

Date: _____ Tooling:

0.00

SPC (Y/N):

Date:

Draw

Number

Date:

Stop

Sequence ID/ Work Center ID

QC

Quality Control

Operation Description

QC8- Inspect parts - second check

Memo

QC: _____ Date: _____

Set Up/ Run Hours

le 10/07/21

Plan Draw Code Rev.

Reject Accept **Qty** Qty

Reject

Insp. Number Stamp

40 8

130

Packaging

Packaging

Identify as per dwg & Stock Location: 459

0.00

0.00

140

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

Memo

0.00

CL1017105

Dart Aerospac	e Ltd
---------------	-------

W/O:			W	ORK ORDER CHAI	NGES		- :			 	
DATE	STEP	PRO	CEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No.		DAD #-	Foult Cot		NOD	V N					
Part No: PAR #: Resolution:											
NCR:				DER NON-CONFOR							
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action S Action Description Chief Eng	Section B	Sign & Date	Verification		Approval Chief Eng	Approval QC Inspector	
						. ** •					
	ļ	·									
						WW.					
NOTE		<u> </u>					L				

Work Order ID: 57716

Parent Item:

D4012-1

Parent Item Name:

Cushion

Comments:

Item Name

IPP RevA: New issue 09.10.28 DD verified by:JLM

revA as per dwg 09.11.18 DD verified by:JLM

Replacement Mfg/ Item ID Purch

Purchased MUHMWT3.500X3.000

UHMW Tubing 3.5" x 3"

Component Item ID/

Primary

Location

Bin

Item

No

IPP RevB:

Last

Location

Route

Seq ID

100

Unit of

Measure Hand

0.0000

Start Date: 14/04/2010

Start Qty: 40.00

Required Date: 22/04/2010

Page 1


Required Qty: 40.00

Remaining Date Qty Status Qty on Qty To Pick Issued Issued 5.2758

M 11495

5.0

Dart Aerospace Ltd W/O: **WORK ORDER CHANGES Approval Approval** DATE **STEP** PROCEDURE CHANGE By Date Qty Chief Eng / QC Inspector Prod Mar Part No: ______ PAR #: ____ Fault Category: _____ NCR: Yes No DQA: ____ Date: _____ Resolution: _____ Disposition: ____ QA: N/C Closed: ____ Date: WORK ORDER NON-CONFORMANCE (NCR) NCR: **Corrective Action** Section B **Description of NC** Verification DATE **STEP Approval Approval** Initial **Action Description** Sign & Section A Section QC Inspector Chief Eng Chief Eng Chief Eng Date



.079

Dart	Aeros	pace	Ltd
------	--------------	------	-----

W/O:												
DATE	STEP	PRO	OCEDURE CH	ANGE	By Date				Qty Approval Chief Eng / Prod Mgr			
	·											
		·										
Part No):	PAR #:	Fault Cat	egory:	_ NCR:	Yes N	lo DQA:		Date: _			
		esolution:						1	Date: _			
NCR:	-		WORK OR	DER NON-CONFORMA	NCE (NCR)						
DATE	STEP	Description of NC			Section B Verifica			ton	Approval	Approval		
DAIL	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng		ign & Date	Section C		Chief Eng	QC Inspector		
-									*			
							1.00					
								İ	ii i			
										بعقيمة مديسه بيوا الرياسان		
										-		
				·				-				
										,		
NOTE							1		L			

DART AEROSPACE LTD	Work Order: 577/6	
	21010	
Description: Cushion	Part Number: 14012-1	
Inspection Dwg: NHO(2 Rev: A	Page 1 of	1

FIRST ARTICLE INSPECTION CHECKLIST										
·	x	First Artic	le	Proto	type					
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Cor	nments			
~ 1 7 A	 	1-7-								
1.45	- 030	1.75	1							
r/.58	±.030	1.610	V/_							
140	+ .50	140								
1.a5	±-030	1.250	/							
1.050	+ 010	1-049								
1.031	12 -010	-032								
-10	+ .030	./00								
094	L AIS	.089								
-0312450	t.010 ± .50	-025 X45°	1							
						`				
	,									
	 									
		-								
				¥3 3 42						
		. =		<u> </u>						
	-									
		<u> </u>	0/				NI/*			
Measured by:	<u> </u>	Audited by:	87		Prototype Ap		N/A			
Date:	10/07/01	Date:	10/07	<u>/01</u> [Date:	N/A			
Rev Date	Change			······································		vised by	Approved			
A Date	New Issue				KJ	/JLM				